

**Mad River Watch Site Profile**

**CLAY BROOK**

**Site Coordinates:** 44.136990, -72.846250

**Site Location Description:** Route 100, Warren, at the base of the Sugarbush Access Road.

**Parking and Access:** Park in the pullout on the west side of Route 100 just passed the Sugarbush Access Road, or in the pullout at the base of the Sugarbush Access Road.

**Sampling Location:** Sample on the southwest side (upstream of bridge) of Clay Brook. Walk down the drainage area on the bank, down several large granite slabs, to the brook. Stay close to the bridge abutments.


**Ease of Access:** Moderately steep, no trail. Rocky with some vegetation.

**Analytes:** Temperature, Conductivity, P, N

**Riparian Buffer Description:** Open banks with large rocks and vegetation, busy traffic intersection, some trees upstream on the south bank. A few small brush piles on banks.

**Naturalist Notes (Ecology, History, Wildlife, Plant Species, etc.):** Relatively disturbed area with Virginia creeper, grasses. Phoebe nesting under the bridge.

**Other Comments:** Be careful with footing. Large granite slabs require good foot placement!



 Field Site

 Parking